



Notice of Drinking Water Treatment Technique Violation (s)

**EL JARDIN WSC PWS 0310022** has violated the treatment technique requirements set by the Texas Commission on Environmental Quality (TCEQ) in Title 30, Texas Administrative Code (30 TAC), Section 290, Subchapter F. Public water systems are required to properly disinfect water before distribution, maintain acceptable disinfection residuals within the distribution system, monitor the disinfectant residual at various locations throughout the distribution system, and report the results of that monitoring to the TCEQ on a quarterly basis.

Inadequately treated water may contain disease-causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such as nausea, cramps, diarrhea, and associated headaches. During MARCH, APRIL, MAY, JUNE AND JULY 2018, sufficient levels of chlorine residual were not met in more than five percent (5%) of monthly samples.

**The following actions are being taken to address this issue:**

**El Jardin WSC has started a more aggressive flushing program to ensure disinfection levels stay above the minimum requirement level of .5 mg/l.**

If you have any questions regarding this matter, you may contact Felipe Cantu - Distribution Manager or Mario Sais - General Manager at (956) 831-9981.

Posted/Delivered on: October 19, 2018